# Sets, Kits, and Outfits, for Shop Equipment Cutting And Welding: Set 2

SC: 4940-95-B14 NSN: 4940-00-264-6206

LIN: W67843

# **System Description**

Provides the necessary components to perform a variety of oxyacetylene welding and cutting operations. Intended for use by all levels of maintenance. MOS: 44B

# This system is not currently in reset.

#### Reset Type

Reset Work (Field Level) - Work performed to correct equipment faults that are performed at the ORG/DS level; performed by unit level soldiers, augmented by contractor as required.

### Reset Strategy

n/a

# Reset Procedures

- Replace worn, broken, missing components IAW supply catalog.

  Reorder consumables IAW SC.

### Reset Responsibility

Unit

### **Reset Location**

This system is not currently in reset.

### - Contact Information -

877.4.PMSKOT (877.476.7568) rock-pm-skot@conus.army.mil